Revised 01/05

CORRES. CONTROL INCOMING LTR NO.

00209 RF05

DUE DATE ACTION

## RECEIVED

## **Department of Energy**

2005 APR 18 A 10: 20

**ROCKY FLATS PROJECT OFFICE** TAPONDENCE 10808 HIGHWAY 93, UNIT A GOLDEN, COLORADO 80403-8200

APR 1 3 2005

		_
DIST.	LTR	ENC
BERARDINI, J.H.	X	
BOGNAR, E.S.	X	
BROOKS, L.	X	
CARPENTER, M.	X	
CIUCCI, J.A.		
CROCKETT, G. A.	X	
DECK, C. A.	Ŋ	
DEGENHART, K. R.	X	
DEL VECCHIO, D.		(
DISTER, T. J.		
FERRERA, D. W.	LX	`
GIACOMINI, J. J.		<u> </u>
GILPIN, H.		Ļ
LINDSAY, D. C.	X	
LONG, J. W.	لبيبا	~~
MARTINEZ, L. A.	<b>*</b>	<u> </u>
NAGEL, R. C.	<b>*</b>	
NESTA, S.	$\vdash$	
NORTH, K.		—— ]
SHELTON, D. C.	₽	
SPEARS, M. S.	Ŋ.	
TUOR, N. R. WIEMELT, K.	13-1	<u> </u>
WILLIAMS, J. L.	4 -	<del></del> ,
ZAHM, C.	X	<u> </u>
ZATIM, C.	<del>  ^-</del>	<b></b> (
7 10. 1 D	┰┤	<del> </del>
Mard, D		— <u> </u>
Woods, D	$\overline{}$	<del></del>
•	1	
Freibolh,C	OX.	<sub>1</sub>

Colorado Division of Water Resources South Platte River Basin Water Division 1 Attn: Greg Hammer

810 9th Street, Suite 200 Greeley, CO 80631

Dear Mr. Hammer:

Enclosed is a videotape copy of the interior of the outlet pipe at Dam C-2. The purpose of this videotaping was to assess the current interior of the pipe and compare it to the condition of the same pipe observed on video taken June 21, 1999. The enclosed video was taken on December 22, 2004. Spacing between the pipe joints has not changed since 1999.

If you have any questions or need additional information, please contact John Stover of my staff at 303-966-9735 or Diana Woods at 303-966-4176.

Sincerely,

Joseph A. Legare, Director **Project Management Division** 

COR. CONTROL ADMIN. RECORD PATS

Enclosure

Reviewed for Addressee Corres. Control RFP

cc w/o Enc: J. Stover, PM

D. Woods, RFCSS

C. Freiboth, K-H

Ref. Ltr. #

**DOE ORDER#** 5400.

Administrative Record

ADMIN RECORD

APR 18 2003

05-DOE-00216

